



Mm d x D	Dimensions				Transmissible		Screws DIN912-12,9		
	L	L0	L1	L2	Torque Nm	Thrust KN	No.	Type	TA Nm
20 x 47	17	22	28	34	290	30	5	M6x20	
22x 47	17	22	28	34	320	30	5	M6x20	
24 x 50	17	22	28	34	370	30	5	M6x20	
25 x 50	17	22	28	34	450	36	6	M6x20	
28 x 55	17	22	28	34	500	36	6	M6x20	17
30 x 55	17	22	28	34	540	36	6	M6x20	
32 x 60	17	22	28	34	770	48	8	M6x20	
35 x 60	17	22	28	34	840	48	8	M6x20	
38 x 65	17	22	28	34	910	48	8	M6x20	
40 x 65	17	22	28	34	960	48	8	M6x20	
45 x 75	20	25	33	41	1750	77	7	M8x25	
50 x 80	20	25	33	41	1930	77	7	M8x25	
55 x 85	20	25	33	41	2450	88	8	M8x25	41
60 x 90	20	25	33	41	2700	88	8	M8x25	
63 x 95	20	25	33	41	3180	100	9	M8x25	
65 x 95	20	25	33	41	3250	100	9	M8x25	
70 x 110	24	30	40	50	5000	141	8	M10x30	
75 x 115	24	30	40	50	5250	141	8	M10x30	
80 x 120	24	30	40	50	5600	141	8	M10x30	83
85 x 125	24	30	40	50	6750	159	9	M10x30	
90 x 130	24	30	40	50	7100	159	9	M10x30	
95 x 135	24	30	40	50	8350	176	10	M10x30	
100 x 145	26	32	44	56	10300	205	8	M12x30	
110 x 155	26	32	44	56	11250	205	8	M12x30	145
120 x 165	26	32	44	56	13900	231	9	M12x30	
130 x 180	34	40	52	64	20000	308	12	M12x30	
140 x 190	34	40	54	68	22250	317	9	M14x40	
150 x 200	34	40	54	68	26300	352	10	M14x40	
160 x 210	34	40	54	68	31000	287	11	M14x40	
170 x 225	44	50	64	78	35900	422	12	M14x40	230
180 x 235	44	50	64	78	38000	422	12	M14x40	
190 x 250	44	50	64	78	50100	528	15	M14x40	
200 x 260	44	50	64	78	52800	528	15	M14x40	
220 x 285	50	56	72	88	64500	587	12	M16x40	
240 x 305	50	56	72	88	88000	734	15	M16x40	355
260 x 325	50	56	72	88	114000	880	18	M16x40	
280 x 355	60	66	84	102	132000	948	16	M18x50	
300 x 375	60	66	84	102	159000	1059	18	M18x50	485
320 x 405	74	81	101	121	220000	1374	18	M20x50	
340 x 425	74	81	101	121	272500	1603	21	M20x50	690
360 x 455	86	94	116	138	308000	1710	18	M22x60	
380 x 475	86	94	116	138	379000	1995	21	M22x60	930
400 x 495	86	94	116	138	399000	1995	21	M22x60	